DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection

Bay Area Branch 690 Walnut Ave.St. 150 Vallejo, CA 94592-1133 (707) 649-5453 (707) 649-5493



Contract #: 04-0120F4

Cty: SF/ALA Rte: 80 PM: 13.2/13.9

File #: 69.28

WELDING INSPECTION REPORT

Resident Engineer: Pursell, Gary **Report No:** WIR-003935

Address: 333 Burma Road **Date Inspected:** 20-Sep-2008

City: Oakland, CA 94607

OSM Arrival Time: 630 **Project Name:** SAS Superstructure **OSM Departure Time:** 1530 **Prime Contractor:** American Bridge/Fluor Enterprises, a JV

Contractor: Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China

CWI Name: CWI Present: Yes No Yes N/A **Rod Oven in Use:** Yes No **Inspected CWI report:** No N/A N/A **Electrode to specification:** Yes No Weld Procedures Followed: Yes No N/A N/A **Qualified Welders:** Yes No **Verified Joint Fit-up:** Yes No N/A N/A N/A **Approved Drawings:** Yes No **Approved WPS:** Yes No Yes No N/A **Delayed / Cancelled:**

34-0006 **Bridge No: Component: OBG** and **SAS** Tower Fabrication

Summary of Items Observed:

On this date, Caltrans Office of Structural Material (OSM) Quality Assurance (QA) Inspector Joselito Lizardo was present as requested to perform observations on the fabrication of Orthotropic Box Girder (OBG) and SAS Tower at Zhenhua Port Machinery Company (ZPMC) facility at Changxing Island, in Shanghai, China.

This QA observed ZPMC/NDE perform MT on the following weld joints. This QA also performed 10% MT on the same weld joints.

- a) BP-144-001-007~018 OBG Bottom Plate fillet welds, found deem acceptable
- b) BP117-001-007~018 OBG Bottom Plate fillet welds, rejected due to 1-transverse linear indication found by ZPMC/NDE
- c) NSD1-SA335-11 found deem acceptable
- d) NSD1-SA335-12 found deem acceptable
- e) NSD1-SA335-15 found deem acceptable
- f) NSD1-SA27B/B-15 found deem acceptable
- g) NSD1-SA27B/B-4 found deem acceptable
- h) NSD1-SA27B/B-8 rejected due to 35mm linear indication found by this QA. Due to this missed indication by ZPMC/NDE, an incident report was issued against ZPMC. See photo below.

WELDING INSPECTION REPORT

(Continued Page 2 of 2)



Summary of Conversations:

No significant conversation ocurred today.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Joshua Ishibashi, (858) 232-7081, who represents the Office of Structural Materials for your project.

Inspected By:	Lizardo,Joselito	Quality Assurance Inspector
Reviewed By:	Cuellar,Robert	QA Reviewer